Check of TS 110512 PAY TFs
- Action IMR>IM, ReadOut TM, no IP here.
- Blue = 10 kg, green = 40 kg, red = 80 kg, all params detail identical

longitudinal


~ OK: we have to check the reason of 0.6 Hz pair, a similar pair is also in transversal (0.57 Hz)

pitch



ОК

transversal

NO: relevant structures OK, but still some differencies in frq. locations and some groups of coupling that are in my case absent (the pair around 0.57 Hz is an example)

roll

NO: group around 5-10 Hz

vertical

OK

Yaw

~ OK: some difference in z/p inversion and position, in one case. It should be checked