

Sensors and actuators

	Filter0	Filter1-3	Filter4	IM-MB	TM-RM
Sensor	ACC(H) x3 ACC(V) x1 LVDT(H) x3 LVDT(V) x1	LVDT(V) x1	LVDT(V) x1 OL x1	PS(H) x4 PS(V) x4 OL x1	PS(H) x4 OL x2
Actuator	MC(H) x3 MC(V) x1	MC(V) x1	MC(V) x1 MC(Y) x1	MC(H) x4 MC(V) x4	MC(H) x4
Motor	STEP(H) x3 STEP(V) x1 PICO(Y) x1		PICO(Y) x1	STEP(H) x2 STEP(V) x2	

ACC: accelerometer, LVDT: linear variable differential transformer PS: position sensor, OL: optical lever, MC: magnet-coil, ES: Electro static, STEP: stepping motor, PICO: picomotor